



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
March 15, 2006

Supervisor *DRH*

Mine Name: Etna Mine
Operator Name: American Cometco, Inc.
Jerry Glazer
155 West 100 South
Hurricane, Utah 84737

Permit number: S/021/009
Inspection Date: February 27, 2006
Time: 12:30 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Inactive

Weather: Sunny, cool

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspected this site to look at the work done by the Abandoned Mines group a year ago.

Inspection Summary:

The main shaft at the site had been closed using a concrete and rebar cap. The subsidence along the entry road had been backfilled, but the fill material in this area had begun to subside.

Photos and a GPS point were taken at the site.

Conclusions and Recommendations:

The site remains inactive; I will continue to monitor the site when I am in the area.

Inspector's Signature

Doug Jensen

Date:

3/15/06

dj:pb

American Cometco, Inc - Jerry Glazer
Will Stokes, SITLA

Attachment: GPS & Photos

O:\M021-Iron\S0210009-EtnaMine\inspection\02272006insp.doc

ATTACHMENT

Photographs

S/021/039, Etna Mine, American Cometco, Inc.
Inspection Dated: February 27, 2006 ; Report Dated: March 15, 2006



Photo 1 Main Shaft Area, Capped shaft at right corner of photo



Photo 2 Subsidence west of main shaft



Photo 3 Subsidence Area

Mine Number: S0210009
Mine Name: Etna Mine
Township 33 S Range 20 W Section 36 SLBM


Inspection Date Feb. 27, 2006
Map Produced by DKS

Acres Disturbed	0
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0
Total Acres Disturbed	
Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend
All items symbolized in legend may not be appear on map

- County Boundary
- Township or range line: location doubtful
- Access
- Mine
- Nonline
- Other
- Interstate
- US Route
- State Route
- Primary Route
- Secondary Route
- PreExisting
- Prelaw
- Main Dirt Road
- Unimproved Road
- Interchange
- Trail
- BLMStateMinerals
- CommunityPit

DOQ imagery date 1998



0 625
Feet

1:7,500 1 inch equals 625 feet

Verify Scale

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.